



Brief glossary

EPAL European Pallet Association e.V. DIN EN 13698-1 Product specification for pallets - Part 1:

fabrication of 800 mm x 1,200 mm wooden flat pallets

Usable For use as intended for storage and transport MFH suitable Machinable, suitable for materials handling (roller and chain-

type conveyor) and storable on high-rise racks

Plant protection related treatment in keeping with IPPC. ISPM15/IPPC

Requirements on industrial drying

Handed over by:

EPAL is represented in Germany by

Gütegemeinschaft Paletten e.V. Benrather Schlossallee 2A • 40597 Düsseldorf

Tel.: + 49 (0) 211 98 49 49 93 Fax: +49 (0) 211 98 49 49 85 info@gpal.de • www.gpal.de

European Pallet Association e.V. Wahlerstr. 28 · 40472 Düsseldorf · Germany · Tel: +49 (0) 211 98 480 48 - 0 · Fax: +49 (0) 211 98 480 48 - 48 · info@epal-pallets.org · www.epal.eu






THE PALLET SYSTEM.

QUALITY **CLASSIFICATION**

for the open pallet exchange pool



Statutory requirement

The pallet considered in this document involves a four-way wooden flat pallet in keeping with DIN EN 13698-1, "Product Specification for Pallets - Part 1: Fabrication of 800 mm x 1,200 mm Wooden Flat Pallets" which as a load carrier under the intended use as a warehouse appliance in keeping with BGR 234 and in the German field in keeping with ProdSG (Product Safety Act) is - as a technical working appliance either as new or in a used condition - is to be marketed and/or provided for the employees.



QUALITY CLASSIFICATION

For the open pallet exchange pool





Usable for STORAGE TRANSPORT MFH 🌣





Usable for STORAGE TRANSPORT MFH ©



CLASS A

Usable for STORAGE TRANSPORT MFH ©



CLASS C

Usable for STORAGE TRANSPORT



NOT USABLE



Hammering down projecting fastening elements





Approved eradication of faults by users for quality classification (A, B, C):





REPAIR only permitted by duly licensed repair company:



Missing component



Visible fastening elements e.g. nails



Inadmissible component

Without being repaired, pallets with these faults must not be used in the open pallet exchange pool



onto the products e.g. paint, oil, smell, mould, mould stains etc.



Stringer, partially or fully fractured board



Inadmissible repair



Skewed block > 1cm



No longer any prescribed identification legible